

77 EPA LETTERHEAD

SDMS Document ID



2030979

February 27, 2004

Ref 8EPR-SR

George Bauer
203 East Spruce Street
Libby, MT 59923

Dear Mr. Bauer:

The U.S. EPA (EPA) and their contractors conducted an inspection of your property. The purpose of the inspection was to identify potential sources of Libby asbestos, such as vermiculite attic insulation, and to collect soil samples if necessary. The inspectors observed vermiculite insulation and vermiculite in the outdoors.

The next step in the clean up process for your property is a Pre-Design Inspection (PDI). A representative from the EPA Information Center will be contacting you in the near future to schedule the PDI. Due to the presence of outdoor contamination, the PDI must be conducted when all the snow has melted in order to properly evaluate any gardens, flowerbeds, or yard soil. After the PDI is complete, a work plan will be developed and your property will be added to the next set of homes slated for clean up.

I do not have a firm date for this clean up, but based on the current status of your property, I anticipate that your property will be cleaned up in late Summer/early Fall of 2004. A Community Involvement Coordinator (CIC) will contact you mid-Summer to discuss the clean up process as well as a more specific time frame for clean up. If you have any questions in the interim, please contact the EPA Information Center in Libby at 293-6194.

Sincerely,

Jim Christiansen
Remedial Project Manager

Status letters

Erica - $\frac{1}{2}$

Patty -

>> EPA letterhead <<

February 27, 2004

Ref 8EPR-SR

Don Benefield
264 Vicks Drive
Libby, MT 59923

Dear Mr. Benefield:

The U.S. EPA (EPA) and their contractors conducted an inspection of your property. The purpose of the inspection was to identify potential sources of Libby asbestos, such as vermiculite attic insulation, and to collect soil samples if necessary. The inspectors observed vermiculite insulation and vermiculite in the outdoors, as well as vermiculite in a pump house on the property.

The next step in the clean up process for your property is a Pre-Design Inspection (PDI). A representative from the EPA Information Center will be contacting you in the near future to schedule the PDI. Due to the presence of outdoor contamination, the PDI must be conducted when all the snow has melted in order to properly evaluate any gardens, flowerbeds, or yard soil. After the PDI is complete, a work plan will be developed and your property will be added to the next group of homes slated for clean up.

I do not have a firm date for this clean up, but based on the current status of your property, I anticipate that your property will be cleaned up in late Summer/early Fall of 2004. A Community Involvement Coordinator (CIC) will contact you mid-Summer to discuss the clean up process as well as a more specific time frame for clean up. If you have any questions in the interim, please contact the EPA Information Center in Libby at 293-6194.

Sincerely,

Jim Christiansen
Remedial Project Manager

77 EPA LETTERHEAD LL

February 27, 2004

Ref 8EPR-SR

Carol Ramos
44 Pine Street
Libby, MT 59923

Dear Ms. Ramos:

The U.S. EPA (EPA) and their contractors conducted an inspection of your property. The purpose of the inspection was to identify potential sources of Libby asbestos, such as vermiculite attic insulation, and to collect soil samples if necessary. The inspectors observed vermiculite insulation and vermiculite in the outdoors.

The next step in the clean up process for your property is a Pre-Design Inspection (PDI). A representative from the EPA Information Center will be contacting you in the near future to schedule the PDI. Due to the presence of outdoor contamination, the PDI must be conducted when all the snow has melted in order to properly evaluate any gardens, flowerbeds, or yard soil. After the PDI is complete, a work plan will be developed and your property will be added to the next group of homes slated for clean up.

I do not have a firm date for this clean up, but based on the current status of your property, I anticipate that your property will be cleaned up in late Summer/early Fall of 2004. A Community Involvement Coordinator (CIC) will contact you mid-Summer to discuss the clean up process as well as a more specific time frame for clean up. If you have any questions in the interim, please contact the EPA Information Center in Libby at 293-6194.

Sincerely,

Jim Christiansen
Remedial Project Manager

→ EPA Letterhead ←

February 27, 2004

Ref 8EPR-SR

Charlene Leckrone
1305 Renwood Drive
Libby, MT 59923

Dear Ms. Leckrone:

The U.S. EPA (EPA) and their contractors conducted an inspection of your property. The purpose of the inspection was to identify potential sources of Libby asbestos, such as vermiculite attic insulation, and to collect soil samples if necessary. The inspectors observed vermiculite in the outdoors.

The next step in the clean up process for your property is a Pre-Design Inspection (PDI). A representative from the EPA Information Center will be contacting you in the near future to schedule the PDI. Due to the presence of outdoor contamination, the PDI must be conducted when all the snow has melted in order to properly evaluate any gardens, flowerbeds, or yard soil. After the PDI is complete, a work plan will be developed and your property will be added to the next set of homes slated for clean up.

I do not have a firm date for this clean up, but based on the current status of your property, I anticipate that your property will be cleaned up in late Summer/early Fall of 2004. A Community Involvement Coordinator (CIC) will contact you mid-Summer to discuss the clean up process as well as a more specific time frame for clean up. If you have any questions in the interim, please contact the EPA Information Center in Libby at 293-6194.

Sincerely,

Jim Christiansen
Remedial Project Manager

→ EPA letterhead ←

February 27, 2004

Ref 8EPR-SR

Jim Davidson
1004 Mineral Avenue
Libby, MT 59923

Dear Mr. Davidson:

The U.S. EPA (EPA) and their contractors conducted an inspection of your property. The purpose of the inspection was to identify potential sources of Libby asbestos, such as vermiculite attic insulation, and to collect soil samples if necessary. The inspectors observed vermiculite insulation and vermiculite in the outdoors.

The next step in the clean up process for your property is a Pre-Design Inspection (PDI). A representative from the EPA Information Center will be contacting you in the near future to schedule the PDI. Due to the presence of outdoor contamination, the PDI must be conducted when all the snow has melted in order to properly evaluate any gardens, flowerbeds, or yard soil. After the PDI is complete, a work plan will be developed and your property will be added to the next set of homes slated for clean up.

I do not have a firm date for this clean up, but based on the current status of your property, I anticipate that your property will be cleaned up in late Summer/early Fall of 2004. A Community Involvement Coordinator (CIC) will contact you mid-Summer to discuss the clean up process as well as a more specific time frame for clean up. If you have any questions in the interim, please contact the EPA Information Center in Libby at 293-6194.

Sincerely,

Jim Christiansen
Remedial Project Manager

Jim Davidson has ^Acontaminated
house on 10th & Mineral Ave.

Since he has been diagnosed with
mesothelioma, he would like to have
some priority on a clean-up plan.

He is concerned that his widow
would have to put up with the clean up.

I feel that he should get some
priority, under his circumstances.

Gary D. Swenson

Jim -

I want to redo my yard. I wanted
to do it last year but waited to see when or
if I was going to have it cleaned by EPA.
How do I go about to see if it can be
done this spring, or if it's suppose to be done.

1305 Renwood Dr.

Thanks.

Charlene

293-7037

WK. 293-3755